

Intelligent Infrared Methane Gas Sensor

(Model: MH-741A)

Manual

Version: 3.3

Valid from: May 1st, 2014

Zhengzhou Winsen Electronics Technology Co., Ltd.

Statement

This manual copyright belongs to Zhengzhou Winsen Electronics Technology Co., LTD. Without the written permission, any part of this manual shall not be copied, translated, stored in database or retrieval system, also can't spread through electronic, copying, record ways.

Thanks for purchasing our product. In order to keep customers using it better and reduce the faults caused by misuse, please read the manual carefully and operate it correctly in accordance with the instructions. If users disobey the terms or remove, disassemble, change the components inside of the sensor, we shall not be responsible for the loss.

The specific such as color, appearance, sizes etc., please in kind prevail.

We are devoting ourselves to products development and technical innovation, so we reserve the right to improve the products without notice. Please confirm it is the valid version before using this manual. At the same time, users' comments on optimized using way are welcome.

Please keep the manual properly, in order to get help if you have questions during the usage in the future.

Zhengzhou Winsen Electronics Technology CO., LTD.

MH-741A Infrared CH4 Gas Sensor

1. Product Description

MH-741A is a universal type intelligent sensor to detect CH4 gas,taking advantage of non-dispersive infrared (NDIR) principle. With high selectivity, no oxygen dependence, high performance and long lifespan features, MH-741A also has built-in temperature compensation feature. MH-741A is a compact and high-performance sensor based on infrared absorption of gas detection technology, micro-machining and sophisticated circuit design.



2. Features

- High sensitivity, high resolution, low power consumption
- > Output method: UART, analog voltage signal, etc.
- Quick response
- > Temperature compensation, excellent linear output
- Excellent stability, Long lifespan
- Anti-poisons, anti-vapor interference
- Detect combustible gas concentration matching with flame-proof marked detector in area 1&2 explosive environments which mix of II A, II B, II C and T1-T6 flammable gases, vapors and air

3. Application

Widely used for industrial field instrumentation, industrial-process control and safety protection

4. Specification Table 1 Technical Index

Product Model	MH-741A				
Gas Detected	Flammable Gas				
Working Voltage	4.5 V ~ 5.5V DC				
Average Current	< 100mA				
Interface Level	3.3V				
Measurement Range	0~100%VOL optional (view table 2)				
Quitaut Ganal	IIC				
Output Signal	0.4-2V DC				
Warm-up Time	3min				
Response Time	T ₉₀ < 30s				
Working Temperature	-40°C ~ 70°C				
Working Humidity	0 to 95%RH, non-condensing				
Dimension	Φ44×61mm				
Weight	350g				
Lifespan	>5 years				
Ex-marking	Ex d II C T6 Gb				
Protected Class	IP65				

Table 2 Measurement Range and Accuracy

Detected Gas	d Gas Measurement Accuracy Range		Remark		
Methane(CH4)	0~5%VOL	0.01%VOL	Temperature compensation		
Methane(CH4)	0~10%VOL	0.01%VOL	Temperature compensation		
Methane(CH4)	0~100%VOL	0.1%VOL	Temperature compensation		

5. Structural Drawing





Figure 1 Structural Drawing of Sensor





Pin	Description
Pad1	V in (input voltage 4.5V \sim 5.5V)
Pad4	GND
Pad5	V out (0.4~2V)
Pad2	IIC(SCL) clock
Pad3	IIC(SDA) data
Pad6, Pad7, Pad8	Reserved, do not connect
Pad10, Pad11, Pad12	

Table 3 Definition of Pin

6. Application Circuit




Figure 3 Application Circuit

7. Explanation

7.1 Analogue Voltage Output

Input 5V voltage to Win Pin, GND Pin connect power ground and Vout Pin connect input side of ADC, then warm-up the sensor, the Vout side will output a voltage value which stands for the gas concentration, while output voltage range 0.4V~2V stands for gas concentration 0~FS. If it found in trouble in self-inspection process, the output voltage of sensor is 0V.




Figure 4 Analogue Voltage Output

7.2 Digital Output

Input 5V voltage to Win Pin, GND Pin connect power ground, CLK side of user's communication interface connect CLK side of detector while SDA side connect SDA side of detector, then the detector will read the value of gas concentration directly through the IIC of the sensor (The pull-up resistor of user's SCL and SDA signal lines must be no more than 10k to ensure the normal work of the communication interface), no need to calculate.

7.2.1 Communication Protocol

MH-741A is communicated through IIC bus. The module works basing IIC slave mode and can connects to external MCU, module address: 0x55, write operation address: 0xAA, read operation address: 0xAB. Every frame number data contains 10 bytes. Different host orders lead to different data and the last byte of data is the proof test value. The SCL clock frequency is recommend less than 10K.

1) Device Address

Address format: Highest seven digits are the module add of the sensor(0x55), the least significant digit is SDIR, 0 stand for Reading, 1 stand for Writing.

A7	A6	A5	A4	A3	A2	A1	W/R
1	0	1	0	1	0	1	0/1

Table 4: Address Format

IIC communication

Write address: 0xAA, Read address: 0xAB

2) Bus Description

IIC interface protocol is a special bus signal protocol, is composed of 3 parts - Start(S), Stop(P) and binary data, as shown below. At start,SCL is high,SDA is at falling edge.Aftter that,send the slave add.After the seven add digits is the control read&write digits,choose the read&write operation as above picWhen the slave device recognizes the corresponding add information,it sends a responsive signal to main device and SDA is pulled down at the ninth clock cycle.At stop,SCL keeps high level,SDA is at rising edge.




Figure 5 IIC Sequence Chart

3) Command

Every frame number data of IIC communication command contains 10 bytes. Different host orders lead to different data and the last byte of data is the proof test value.

Table 5 Command List

0x96	Gas Concentration
0xA0	Calibrate zero point (ZERO)
0xAA	Calibrate span point (SPAN)

Gas Concentration Reading

1	0x96	Gas Con	Gas Concentration Reading									
Send	0	1	2	3	4	5	6	7	8	9		
	Command									Check		
	Command									Code		
	0x96	0x00	0x00	0x00	0x00	0x00	0x00	0x00	0x00	0x6A		
EXP.	96 00 00 00 0	0 00 00 00	0 00 6A									
	0	1	2	3	4	5	6	7	8	9		
Return	Module					High	Low	High	Low	Check		
	Status					Density	Density	Range	Range	Code		
EXP.	Return											

Gas concentration= high density *256 + low density

Calibrate Zero

1	0xA0	Gas Concentration Reading									
Send EXP.	0	1	2	3	4	5	6	7	8	9	
	Comma									Check	
Send	nd									Code	
	0xa0	0x00	0x00	0x00	0x00	0x00	0x00	0x00	0x00	0x60	
EXP.	A0 00 00	00 00 00 00	00 00 60								
	0	1	2	3	4	5	6	7	8	9	
Return			-	-		-			-		
EXP.	No value r	eturn									

Calibrate Span

1	0xAA	Gas Conce	Gas Concentration Reading									
	0	1	2	3	4	5	6	7	8	9		
Send	Comma nd	SPAN Value								Check Code		
	Охаа	High Byte	Low Byte	0x00	0x00	0x00	0x00	0x00	0x00	0xbb		
EXP.	AA 13 88	00 00 00 00	0 00 00 00 00 BB (Eg. calibrate 5000ppm, HEX: 0x1388)									
	0	1	2	3	4	5	6	7	8	9		
Return						-		-	-			
EXP.	No value r	eturn										

7.2.2 Calibrate and Calculate

The checksum = (invert (byte0 + ... + 8)) + 1

For example, Gas	Concentration Reading
------------------	-----------------------

	Command Sent										
Byte0	Byte1	Byte2	Byte3	Byte4	Byte5	Byte6	Byte7	Byte8	Byte9		
Command	-	-	-	-	-	-	-	-	Check		
									Value		
0x96	0x00	0x00	0x00	0x00	0x00	0x00	0x00	0x00	0x6A		

A. Add all the bytes together except byte $\ensuremath{\mathbf{0}}$

0x96 + 0 + 0 + 0 + 0 + 0 + 0 + 0 + 0 = 0x96

- B. Get the value from step A, then invert it. 0xff - 0x96 = 0x69
- C. Plus one based on the value of step B 0x69 + 0x01 = 0x6A

7.2.3 Example Program

C Language Calibrate & Calculate and Routine

```
char getCheckSum(char *packet)
{
    char i, checksum;
    for( i = 1; i < 9; i++)
    {
        checksum += packet[i];
    }
      checksum = 0xff - checksum;
    checksum += 1;
    return checksum;
}</pre>
```

8. Notes For Maintenance

8.1 The sensor should be calibrated regularly. Recommended cycle time is once per 6 months.

8.2 Do not use the sensor in the high dusty environment for long time.

8.3 Please use the sensor with correct power supply.

Zhengzhou Winsen Electronics Technology Co., LtdAdd.: NO.299 Jinsuo Road, National Hi-Tech Zone,Zhengzhou, 450001 ChinaTel.: 0086-371-67169097Fax: 0086-371-60932988E-mail:sales@winsensor.comWebsite:www.winsentech.com